

Original post set 1820 by Laughlin with witness: 10" buckeye N $\stackrel{?}{,}$ W 22 links; 12" sugar S 30 W 14 links per Marion County Atlas pg. 7. Survey by O.W. Voorhis 3-2-1864 called no stone but stated original witness trees were standing per Pike Township Legal Survey Book pg. 11. Monroe 7-3-51 called 1/2" pipe over stone. Long 1-6-59 called same. McCarty 8-13-86 called called railroad spike over steel pin. Excavated by Wilcoxen 8-29-98 and railroad spike was found at surface. Steel pin found 9" down. Harrison set. Re-tied 11-09-03.

16030504		
REF.	DISTANCE	DESCRIPTION
1.	50.59	Road nail E PwP#64-298 B 4"up
2.	122.27'	Road nail N PwP#63-328 A 6"up
3.	15.74	PK nail NE corner fence post
4.	49.09	Mag nail w/brass washer N PwP#57-327 A 4"up
5.	154.28'	Top nut of fire hydrant
6.	51.56'	Mag nail w/brass washer SW PwP#279-297 B 4"up
-		